TECHNICAL INFORMATION MEMO

SUBJECT	date
TX750 ENGINE TROUBLESHOOTING BULLETINS (Additional bulletin copies for handy reference)	July 20th, 1973 ATTENTION: Yamaha Service Managers

CONTENTS

BULLETIN NUMBER	SUBJECT
327	PRIMARY GEAR NOISE
332	BALANCER CHAIN NOISE
333	OIL LEAKS, Top End
334	UPPER CASE BLIND PLUG WELDING INSTRUCTIONS
335	CAM CHAIN TENSIONER NOISE
336	STARTER CLUTCH NOISE
337	IRREGULAR CLUTCH ENGAGEMENT
338	OIL LEAKS, Ignition Point Area
345	OIL LEAK, Lower Crankcase Studs

INDEX

SYMPTOM	BULLETIN NUMBER
I. Mechanical Engine Noise	
A. Clattering, top end (idling)	335
B. Clattering, right side of crankcase (idling)	327
C. Whining, right side of crankcase (decelerating)	327
D. Knocking or clattering, left side of crankcase (while starting and/or idling)	336
E. Rasping from crankcase (decelerating from moderate speeds)	332
II. Engine Oil Leaks	
A. Cylinder and head area	333
B. Upper crankcase blind plug (below carbs)	334
C. Ignition point area	338
D. Bottom of crankcase	345
III. Irregular Clutch Engagement	
A. Jerky or grabbing engagement	337

July 20, 1973

WARRANTY BULLETIN


Gentlemen:

When checking TX750's for excessive engine noise and oil leaks on a warranty basis, be sure that you read the warranty section in the Motorcycle Service News Bulletins which pertain to this model. As you may note, to avoid claim rejection you must be sure to use the correct problem code, the correct job code and the correct flat rate time as advised under the warranty section on each Motorcycle Service News Bulletin covering the difficulty which you are correcting.

To maintain good customer relations and to assist you in correcting problems which may arise with the TX750, Yamaha International Corporation has arranged for engineering purposes a limited warranty extension of three months on these particular repair procedures. In addition to this, to enable us to maintain our leading position in the motorcycle industry, we have not restricted the warranty extension as to mileage. When following these special procedures, please try to be as meticulous as possible to correct the problem on a first time repair to ensure customer satisfaction.

Should you have any questions regarding the warranty coverage on the TX750 which you do not feel are answered in the Motorcycle Service News Bulletins or in our standard warranty policy, please get in touch with us immediately so that we may assist you in coping with problems which you may be experiencing. The full cooperation which you have extended to us in the past in correcting unforeseen mechanical problems has been extremely helpful and we look forward to its continuance in overcoming these present difficulties.

Very truly yours,



William W. Thomas
National Warranty Manager

WT:js