MOTORCYCLE SERVICE NEWS

NUMBER 313

PAGE 1 of 1

YAMAHA INTERNATIONAL CORPORATION
BUENA PARK, CALIFORNIA 90620
DATE 3/6/73

TX750 — CLUTCH, Loose Spring Screws

It will be necessary to retighten the clutch spring screws, Ref. 13-9, Part No. 256-16337-00, on TX750 Engine Numbers 18192～19758. It is unnecessary to drain the crankcase oil if machine is laid down on its left side.

WARRANTY INFORMATION

Standard warranty procedure will apply. Use Failure Code 90C. Use Job Code 2604 for .9 hours warranty labor credit. If several machines are being serviced at the same time, you may use the group claim procedure as shown on Page 21 of the Dealer's Warranty Handbook.

† † † † † †