MOTORCYCLE SERVICE NEWS

NUMBER 346


PAGE 1 of 1

YAMAHA INTERNATIONAL CORPORATION
BUENA PARK, CALIFORNIA 90620

DATE 8/13/73

TX750 CRANKSHAFT AND ROD JOURNALS, Size Code Location Change

Main Bearing and Rod Bearing journal sizes are identified by code numbers stamped on the webs. The locations of these code numbers have been changed. The illustration below shows the new number location and the journal applicable to that location.



Currently, production units are still using the old numbering system. Crankshafts from parts stock, however, employ the new system.

NOTE:

For additional information regarding size codes, see Motorcycle Service News Bulletin Number 302, pages 3~4.

† † † †