MOTORCYCLE PARTS NEWS

NUMBER 370

PAGE 1 of 1

YAMAHA INTERNATIONAL CORPORATION
BUENA PARK, CALIFORNIA 90620
DATE 4/12/73

TX750 — CRANKCASE ASSEMBLY, Replacement Part with Shafts

Replacement crankcase assemblies are now available with crank balancer shafts (2) and bearings (4) fitted and installed. The shafts and bearings on these assemblies are matched for machine tolerances to prevent excessive noise. When replacing a TX750 crankcase assembly (crankcase halves are not sold seperately), it is advisable to order this new assembly with the fitted balancer shafts and bearings.

Attached is a stick-on overlay for Page 52 of the TX750 Parts List. Tear off backing paper and cover existing parts reference list.

PARTS ORDERING INFORMATION

Ref. No.	New Part No.	Description	Qty.	Price/Discount
18-0-2	341-15109-14-00	CRANKCASE ASSY.	1	$187.31-B
(includes)	. 341-15111-05-00	. CASE, crank upper	1	
	. 341-15121-12-00	. CASE, crank lower	1	
	. 91810-05016	. PIN, dowel (8.4-12-16)	1	
	. 341-11455-30-00	. SHAFT 1	1	
	. 341-11465-30-00	. SHAFT 2	1	
	. 93311-52510	. BEARING 1	2	
	. 93311-42009	. BEARING 2	2	

AFFECTED MACHINES

NONE – Parts are supplied for replacement purposes only.

SALE OF PARTS

1. Old type Crankcase Assembly, P/N 341-15100-14-00 will be available until present stock is depleted.
2. New type Crankcase Assembly is available now.

PLEASE BRING YOUR PARTS LIST UP-TO-DATE!

† † † †