MOTORCYCLE PARTS NEWS

NUMBER 392

PAGE 1 of 1

YAMAHA INTERNATIONAL CORPORATION
BUENA PARK, CALIFORNIA 90620

DATE 8/21/73

TX750 — PARTS LIST CORRECTION, Alternator Rotor Assembly

The TX750 and TX500 Rotor assemblies are interchangeable. Please correct your TX750 Parts List as follows:

REF. NO.	BOOK READS	SHOULD READ	DESCRIPTION	QTY.	REMARKS
9-1	341-81650-12-00	371-81650-10-00	ROTOR COMP.	1	See Below

NOTE:

The 341 Rotor will no longer be stocked. Only the 371 (TX500) type will be sold.

PLEASE BRING YOUR PARTS LISTS UP-TO-DATE!

† † † †