TECHNICAL BULLETIN

MOTORCYCLE
M4-065

TX750

CONNECTING ROD CHANGE

The factory has redesigned the TX750/750A connecting rods to improve the reliability.

PARTS ORDERING

PAGE	REF. NO.	BOOK NOW READS	BOOK SHOULD READ	PRICE
12	4-0-1	341-11650-00-00	341-11650-02-00	$33.49-B

PLEASE BRING YOUR PARTS LIST UP-TO-DATE!

† † † †

©YAMAHA INTERNATIONAL CORPORATION, BUENA PARK, CALIFORNIA 7/25/74